


# JOB PROGRESS REPORT TO CUSTOMER

JOB DETAILS	
VESSEL TYPE:	25m Utility Vessel
REPORTED TO:	Kumal Petroleum
DATE:	25 <sup>th</sup> February 2025
HULL NO.:	MOC 211

#### **CONTENT:**


Photos below demonstrating job progress till 25<sup>th</sup> Feb 2025

#### 1. Tiller room chequer plating












### 2. Panel fitting










## 3. Console equipment fitting





### 4. Crane installation and operation



